

9. Drawing PIRINEOS 1000



**PARTS BREAKDOWN DIAGRAMME PIRINEOS 1000.**

	DENOMINACION	POS	DENOMINACION
1	Chassis	34	Internal plate (22.2 mm)
2	Leg	35	Diamond disc (Ø 200 mm)
3	Cont leg	36	External plate
4	Screw DIN 603 M8x55	37	Left hand thread nut M.20
5	Washer DIN 9021 Ø 8	38	Head
6	Butterfly nut M8	39	Handle
7	Screw Hex. M10x60	40	Hex screw M10x30
8	Washer DIN 9021 Ø 10	41	Head bearing set
9	Self-locking nut M 10	42	Washer DIN 125 Ø 10
10	Cutting table	43	Nut Hex. M10
11	Left rubber	44	Cables pip
12	Right rubber	45	Housing
13	Butt cut	46	Cooling system
14	Wing M.8	47	Plug tray
15	Washer DIN 9021 Ø 8	48	Submergible pump
16	Screw DIN 603 M8x16	49	Cutting gauge
17	Screw DIN 603 M6x16	50	
18	Butterfly nut M6	51	
19	Goniometer	52	
20	Allen key	53	
21	Key	54	
22	Bridge	55	
23	Left bridge pier	56	
24	Right bridge pier	57	
25	Sheet metal screw thread	58	
26	Screw DIN 603 M8x35	59	
27	Washer DIN 9021 Ø 8	60	
28	Wing M8	61	
29	Self-locking nut M 8	62	
30	Washer DIN 9021 Ø 8	63	
31	Hex screw M8x16	64	
32	Electricity supply box	65	
33	Motor 1,1 Kw.	66	